

24 DEC 68 16 50Z

out 66699

P 241633Z DEC 68  
FM NPIC WASHDC  
TO RHCOAAA/SAC OFFUTT AFB OMAHA NEB  
RHCOAAA/544TH ARTW OFFUTT AFB OMAHA NEB  
RUCLEGA/102TH SRW OL 19 MCCOY AFB FLA  
RUWJDBA/100TH SRW DAVIS MONTHAN AFB ARIZ  
RUEBJRA/NAVRECONTECHSUPPCEN SUITLAND MD  
RUEAIIA/CIA WASH DC  
RUEOJFA/DIA  
RUWBKNA/15TH AF WARCH AFB RIVERSIDE CALIF  
RUEFHQA/HQS USAF  
BT

S E C R E T CITE NPIC 5337.  
SAC FOR DIR, DOSR, DISO, 15TH AF FOR DI DO; 100TH SRW FOR  
CO, DCOI; HQ USAF FOR DIA FOR DIAXX-2.  
FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

SUBJ: EVALUATION OF GLASS LAMP MISSION G-061.

1. IMAGE QUALITY: THE OVERALL IMAGE QUALITY OF THIS MISSION IS GOOD. THERE IS A NOTICEABLE CHANGE IN IMAGE QUALITY ACROSS THE FORMAT FROM THE NON-DATA BLOCK END OF FRAME (GOOD) TO THE

DISTRIBUTION		
CY	OFFICE	PI
1	FILE	
2	CASUAL SEC.	
	EXPROG	
	SECUR	
3	TSSG 25X1	✓
	SEC/OC	
	RND	
4	EXPROG	
	AND	
	ITG	
5	PROD	
	EXPROG	
6	WIDE	
	REST	
	MS	
	FCM	
7	IAS	
	DIR-TRA	
	SPAD	
	25X1	
	CMZ	

ADVANCE CY  
SANITIZED  
WITH TEXT

PAGE 2 RUEADJU 0147 S E C R E T  
DATA BLOCK END OF FRAME (FAIR). INTERPRETATION SUITABILITY OF THIS MISSION IS GOOD. CLOUD COVER AND HAZE OBSCURE APPROXIMATELY 30 PERCENT OF THE ENTIRE MISSION.

2. MISSION DATA:

A. GLASS LAMP MISSION G-061 WAS FLOWN ON 22 DECEMBER 1968 USING "B" CAMERA UNIT 10.

B. FILM TYPE 3431 WAS USED THROUGHOUT. THE RIGHT SIDE WAS PROCESSED TO AN AVERAGE GAMMA OF 2.31; THE LEFT SIDE WAS PROCESSED TO AN AVERAGE GAMMA OF 2.35. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

3. ORIGINAL NEGATIVE:

A. EXPOSURE: EXPOSURE IS ADEQUATE THROUGHOUT THE MISSION.

B. DENSITY AND CONTRAST: GENERALLY MEDIUM FOR THE ENTIRE MISSION.

C. IMAGE DEGRADATIONS:

(1) BOTH SIDES: SLIGHT FOGGING APPARENTLY ASSOCIATED WITH CAMERA START-UP IS PRESENT IN FRAMES 1, 6 AND 9. MINOR EDGE FOG IS PRESENT ALONG THE INBOARD EDGES THROUGHOUT. PLUS DENSITY AREAS ASSOCIATED WITH ROLLER CHATTER ARE PRESENT ALONG BOTH INBOARD EDGES FOR THE FIRST 400 FRAMES.

PAGE 3 RUEADJU 0147 S E C R E T

D. PHYSICAL DEGRADATIONS:

(1) 9R SIDE: THREE HEAT SPLICES AND ONE MANUFACTURING SPLICE ARE PRESENT IN THE MATERIAL.

(2) 9L SIDE: TWO HEAT SPLICES AND ONE MANUFACTURING SPLICE ARE PRESENT IN THE MATERIAL.

E. AUXILIARY DATA: THE EVENTS COUNTER REGISTERED 029 FOR TWO FRAMES, ALL OTHER DATA RECORDING EQUIPMENT FUNCTIONED PROPERLY.

F. OTHER: THERE IS A BIAS OF FIVE BETWEEN THE TITLED FRAME NUMBERS AND THE EVENTS COUNTER AT THE BEGINNING OF THE MISSION. THE LAST TITLED FRAME IS 2683, COUNTER NUMBER 2692.

4. POSITIVES:

A. PRINTING AND PROCESSING ARE GOOD.

GP-1

S E C R E T

---END OF MESSAGE---